



**HONEYWELL SILENT KNIGHT**

12 Clintonville Road  
Northford, CT 06472  
www.silentknight.com

October 19, 2021

**Honeywell Silent Knight 6000 Series Firmware 6.04.03 and HFSS 3.4.1.2710 Release Notes**

The Honeywell Silent Knight 6000 Series addressable fire alarm control panels (FACPs) were designed to accept panel firmware updates through a connected PC. To update the panel firmware, download the latest “Firmware Update Utility 6.02.50 Application.exe” file to a PC, connect the PC to a 6000 Series fire panel using a USB cable and run the Update Utility file.

Updating your panel to the latest released firmware is highly recommended in order to fix known issues and add additional features and product support. Please note: upgrading firmware may take up to 20 minutes and may cause the panel to reboot several times.

Please visit [www.silentknight.com](http://www.silentknight.com) to download the latest panel firmware and programming software.

**Honeywell Silent Knight 6000 Series firmware version 6.04.03 includes the following enhancement:**

- Improves Positive Alarm Sequence (P.A.S.) functionality. This functionality enables the “acknowledge” button on the panels or remote annunciators to initiate a positive alarm sequence. Existing systems with P.A.S. enabled through the use of external UL listed switches per zone will still function normally as programmed.

**Honeywell Fire Software Suite (HFSS) version 3.4.1.2710 includes the following update:**

- Supports Spanish language settings in Microsoft Windows 10 operating system

**Important firmware and programming notes:**

- HFSS version 3.4.1.2710 is required to configure Honeywell Silent Knight 6000 Series FACPs using firmware version 6.04.03
- If Honeywell Silent Knight 6000 Series FACPs are connected through a common communications/annunciation linked system, all FACPs in the system must use the same firmware version